

BTMA Water Service Line Inventory




Brighton Township
1300 Brighton Road
Beaver, PA 15009


Water Service Line - PaDEP Classification

- Galvanized Requiring Replacement
- Lead Status Unknown
- Non-Lead
- Streams
- Hydro Areas
- Parcel Boundary
- Buildings
- Brighton Township
- Municipal Boundary

Date Exported: 11/5/2024 8:44 AM



0 2,000 4,000
1 inch equals 2,000 feet




Revision Number	Date	Description
1	10/05/2024	Initial PaDEP Submission



546 Fourth Avenue
Corryville, PA 15109
(412) 204-4000
Email: info@lsse.com

LSSE • Rabell • Senate



N:\PROJ\212124-52 LCR Water Service Line Inventory\gis\24-52-BTMA - LCR Water Service Line Inventory.aprx|BTMA - SL - Services Line Inventory